THIS DOCUMENT IS TRUE AND CORRECT AT TIME OF PUBLICATION. CONTINUED PRODUCT IMPROVEMENTS MAKE SPECIFICATIONS AND MEASUREMENTS SUBJECT TO CHANGE WITHOUT NOTICE.


## NOTES:


1 5874PBF (ITEM 2) INCLUDES VRK5874 CARTRIDGE ASSEMBLY (ITEM 3) AND PBA6 FLANGED PUSH BUTTON (ITEM 4).

2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.

	ITEM	DESCRIPTION	1117LN
	1	BUTTON, PUSH, FLANGED, PCP W/ VALVE	5874PBF
	2	VALVE REPAIR KIT	VRK5874
	3	PUSH BUTTON ASSY	PBA6
	4	BUBBLER HEAD ASSY, PCP	5703M
	5	STRAINER, WASTE ASSY	6462
	6	TRAP	0005982900
(OPTIONAL)	7	PLATE MOUNTING	6700.4
	8	PLATE BOTTOM	PBM1107

2 REMOVED TO SOLUTION OF THE PARTY OF THE PA





## PARTS BREAKDOWN



1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM WEBSITE: WWW.HAWSCO.COM

D. REVISED PER BY LECK: 5255 JP MODEL(S)

| DATE | CHKD | 1117LN

PART NUMBER
0580000675
REVISION
2

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.