THIS DOCUMENT IS TRUE AND CORRECT AT TIME OF PUBLICATION. CONTINUED PRODUCT IMPROVEMENTS MAKE SPECIFICATIONS AND MEASUREMENTS SUBJECT TO CHANGE WITHOUT NOTICE.


NOTES:

- 1 5874PB (ITEM 3) INCLUDES VRK5874 CARTRIDGE ASSEMBLY (ITEM 4) AND PBA7 FLANGED PUSH BUTTON (ITEM 5).
- 2 ENSURE TUBE IS DISCONNECTED FROM PUSH BUTTON VALVE BODY PRIOR TO REMOVAL. APPLY ONE DROP OF LOCTITE 222MS TO NOZZLE THREADS PRIOR TO FASTENING BACK ONTO BUBBLER HEAD. RE-ATTACH TUBE TO VALVE.

3 USE MODEL 6250LF WITH ACCESS PLATE, PN 0004499489.

	ITEM	DESCRIPTION	PART NO.
	1	STRAINER WASTE ASSY, PCP	6466
	2	BUBBLER HEAD ASSY, PCP	5703M
	3	BUTTON, PUSH, NON-FLANGED, PCP	5874PB
	4	VALVE REPAIR KIT	VRK5874
	5	PUSH BUTTON ASSY	PBA7
*	6	VALVE, BIB FAUCET, PCP	6250LF

^{*} DENOTES OPTIONAL PART.



PARTS BREAKDOWN



1455 KLEPPE LANE SPARKS, NEVADA 89431 (775) 359-4712 FAX (775) 359-7424 E-MAIL: HAWS@HAWSCO.COM WEBSITE: WWW.HAWSCO.COM

WHEN ORDERING PARTS PLEASE SPECIFY MODEL NUMBER.

NNC. REVISED PER BY LECK: 5258 JP LECK: 5258 JP LECK: 5258 GC REVISION TO LICOM 11/25/95 GC REVISION TO LICOM 11/25/95 DATE FV 11/23/17 SCALE: 1:4 DRAWING TYPE: PARTS BREAKDOWN SIZE: A SHEET 1 OF 1